DQA:		<u></u>	Date:						•					TRAC"
			Data			WORK ORDER NON-	-CC	ONFO	RMANCE / UPDATE	14/	ork Ordon u	adata anlız	_	AEROSPACE
QA Closed:			Date:					ľ		VV	ork Order u	date only		
Work Orde	er:					DISPOSITION			AGAINS	T DE	PARTMENT	/PROCESS		
	•				_	Rework			Skid-tube Crosstub	e]	Water Jet		Engineering
Part N	lo.					Scrap			Machining Small Fa	-	Pro	d. Eng. Coor.	┪	Quality
	•					Use-as-is			moforming Finishin	g	4	re/Packaging		Other
NCR N	lo.					Suspected Unapproved			Large Fab Composit	e		Supplier		
		···										·		
Root					Desci	ription of work order update	1	Initial	Action		Sign &	_		
Cause	4	Date	Step	Qty		or non-conformance	Ch	ief Eng	Description		Date	Verification	4	QC Inspector
Design														
Doc/Data	4					,								
Equip/Tooling	\dashv										,		- 1	
Handling/Pre	_											•	- 1	
Material	_					·							- 1	
Operator	\dashv													
Offset/Setup	_												- 1	
Process	\dashv												- 1	
Supplier													- 1	
Training Transport														
Unapproved	\dashv													
опаррточеа			L	l	<u> </u>		FAI	ULT CA	TEGORY		L	L		
Landii	ng G	Gear				General				·		• /		
[_	Bending				Bend		Folio/F	Program		Outside Dim	ensions	T]ı	Pressure/Forced
		Centre No	t Concer	ntric		BOM/Route		Grain			Over/Under	tolerance	-	Set-up
		Cracks				Broken/Damage/Defect		Hardwa	are		Part Incorre	cí [-	Temperature/Cure
		Crimp/Kir	ık/Ripple	/Wave		Burrs		Inspect	ion Incomplete/Unqualified		Part Lost/M	issing	<u></u>	Weld
		Cuffs				Contamination		Instruc	tions Incomplete/Unclear		Part Moved		<u></u>	Wrong Stock Pulled
		Crushing				Countersink		Misali	gned/off center		Positioned V	Vrong _		
		Heat Trea	t			Cut Too Short		Mislab	eled		Power Loss/	Surge		Other
		Inspection	n Strip in	Tube		Drawing	<u> </u>	Misrea	d					
		Marks/Ch	atter		<u> </u>	Drill Holes	L	Off-set						
:		Turning S	-		<u> </u>	Finish		-i	Calibration					
		Wave/Tw	ist in Tuk	oe .		Fit/Function		Out of	Sequence					

DQA:			Date:								,		TRACC
						WORK ORDER NON	-CC	ONFO	RMANCE / UF			_	AEROSPACE
QA Closed:			Date:							V	Vork Order u	odate only	
Work Orde	· ·					DISPOSITION				AGAINST D	EPARTMENT	/PROCESS	
WOIK Old	٠				—	Rework	ıl		Skid-tube	Crosstube	٦	Water Jet	Engineering
Part N	lo.					Scrap	1		Machining	Small Fab	Pro	d. Eng. Coor.	Quality
,	•					Use-as-is	1		noforming	Finishing	-	re/Packaging	Other
NCR N	lo.					Suspected Unapproved			Large Fab	Composite		Supplier	
			,										
Root					Desci	ription of work order update	1	Initial	Acti		Sign &		
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Descr	iption	Date	Verification	QC Inspector
Design													
Doc/Data							ŀ						
Equip/Tooling			ł										
Handling/Pre													
Material													
Operator							l			·			
Offset/Setup													
Process									'				
Supplier										•			
Training			•				İ						
Transport		!				·							
Unapproved							<u> </u>						
							FA	ULI CA	TEGORY	· · · · · · · · · · · · · · · · · · ·			
Landi	ng G	1				General		11:- //		r			Pressure/Forced
	Н	Bending				Bend BOM/Route	\vdash	4	Program	-	Outside Dim	—	Set-up
		Centre No	ot Concer	ntric	<u> </u>	BOM/Route	\vdash	Grain		. -	Over/Under Part Incorre	}	Temperature/Cure
	-	Cracks	- I. /D: I	h	-	Broken/Damage/Defect	-	Hardwa		have lifted	Part Lost/M	-	Weld
	-	Crimp/Kir	тк/кірріе	y wave	-	Burrs	\vdash	4 '	ion Incomplete/Un tions Incomplete/U		Part Moved	·	Wrong Stock Pulled
	\vdash	Cuffs			\vdash	Countariel	-	4	•	-	Positioned \	-	Wrong Stock Fulled
	\vdash	Crushing			\vdash	Countersink Cut Too Short	-	Mislab	gned/off center	-	Power Loss		Other
	\vdash	Heat Trea		Tubo	-	Drawing	-	Misrea		L		Juige	Journal
	\vdash	Marks/Ch		rube	-	Drill Holes	-	Off-set					
	\vdash	Turning S				Finish	\vdash	-	Calibration				
		Wave/Tw	•		\vdash	Fit/Function	\vdash	-	Sequence				
I	1	I ** a v c/ i v	ist iii iut	,	1	11.19.1 01100011	1	10000	ocque, ice				

Packaging

Packaging

Memo

9-0

DQA:			Date:			WORK ORDER NON	~	SNEOI		DDATE				`DART
QA Closed:			Date:			WORK ORDER NON-	-((JNFOI	RIVIAINCE / U		Wo	rk Order up	date only	AEROSPACE
						DISPOSITION				AGAINST	DEP	ARTMENT	/PROCESS	
Work Orde	er: -					Daaul			Skid-tube	Crosstube			Water Jet	Engineering
Part N	do					Rework Scrap			Machining	Small Fab	\dashv	Pro	d. Eng. Coor.	Quality
raiti	•0.					Use-as-is			noforming	Finishing	一		e/Packaging	Other
NCR N	No.					Suspected Unapproved			Large Fab	Composite	ㅓ	,	Supplier	
	-								_	· ·				
Root					Desci	ription of work order update	1	Initial	Act	ion		Sign &		
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Desci	ription		Date	Verification	QC Inspector
Design														
Doc/Data	Ш													
Equip/Tooling	Щ													· ·
Handling/Pre														
Material														
Operator	Н													
Offset/Setup	\dashv													
Process	\vdash											;		
Supplier Training	Н													
Transport	H													
Unapproved	H											:		
							FAI	ULT CA	regory		1			· · · · · · · · · · · · · · · · · · ·
Landi	ng G	iear		-		General			,			*****		
		Bending				Bend		Folio/F	rogram			Outside Dim	ensions	Pressure/Forced
		Centre No	ot Concer	ntric		BOM/Route		Grain				Over/Under	tolerance	Set-up
•		Cracks				Broken/Damage/Defect		Hardwa	ire			Part Incorred	: L	Temperature/Cure
	Щ	Crimp/Kir	nk/Ripple	/Wave		Burrs		Inspect	ion Incomplete/Ui	nqualified	_	Part Lost/Mi	ssing	Weld
	_	Cuffs				Contamination		4	ions Incomplete/l	Jnclear		Part Moved	L	Wrong Stock Pulled
:	${oldsymbol{ o}}$	Crushing				Countersink	<u> </u>	4	ned/off center		$\overline{}$	Positioned V		7
i	${f H}$	Heat Trea			<u> </u>	Cut Too Short	_	Mislabe				Power Loss/	Surge	Other
	${f o}$	Inspection		Tube	\vdash	Drawing		Misread			-			
	-	Marks/Ch			<u> </u>	Drill Holes	<u> </u>	Off-set			-			
	Н	Turning S			\vdash	Finish	\vdash	4	Calibration		-			
	ιl	Wave/Tw	ust in Tub	e e		Fit/Function	Ī	JOUT OF	Sequence					

DQA:			Date:										
						WORK ORDER NON-	-CC	ONFO	RMANCE / UPDAT	E			AEROSPACE
QA Closed:			Date:							Wo	ork Order up	date only	
Work Orde	. r.					DISPOSITION			AG	AINST DE	PARTMENT	PROCESS	
WOIK OIG	=1.		<u></u>			Rework	ı İ		Skid-tube Cros	sstube	l	Water Jet	Engineering
Part N	J۵					Scrap			> —√	all Fab	Pro	d. Eng. Coor.	Quality
1 4101	•••					Use-as-is			~ —	nishing	l	e/Packaging	Other
NCR I	No.					Suspected Unapproved			~ —	posite		Supplier	1
						· · · ·	'		° Ш	· <u> </u>			
Root					Desci	ription of work order update	ĺ	nitial	Action		Sign &		
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Description		Date	Verification	QC Inspector
Design													
Doc/Data													
Equip/Tooling													
Handling/Pre													
Material													
Operator						•							
Offset/Setup													
Process									•				
Supplier				,		·							
Training			•										
Transport													
Unapproved									TECODY.				
1 41							FA	ULI CA	TEGORY				
Landi	_	Bending				General Bend	$\overline{}$	احمانه (ر	Program		Outside Dim	onsions [Pressure/Forced
	┝	Centre No	nt Concer	ntric	-	BOM/Route	<u> </u>	Grain	riogram	-	Over/Under		Set-up
		Cracks	or concer	ILIIC	_	Broken/Damage/Defect	┢	Hardwa	are	i	Part Incorred		Temperature/Cure
•	 -	Crimp/Kir	nk/Rinnle	/\/\ave	-	Burrs	-	4	ion Incomplete/Unqualific	ed	Part Lost/Mi		Weld
	-	Cuffs	потпрыс,	, wave		Contamination	┢	1	tions Incomplete/Unclear	_	Part Moved		Wrong Stock Pulled
•	-	Crushing				Countersink		1	gned/off center		Positioned V	∟_ Vrong	
	-	Heat Trea	ıt			Cut Too Short	H	Mislab	-		Power Loss/		Other
	\vdash	Inspection		Tube		Drawing	\vdash	Misrea		<u> </u>	ı	·	
	\vdash	Marks/Ch	-			Drill Holes		Off-set			·		-
		Turning S				Finish		Out of	Calibration				
		Wave/Tw				Fit/Function		Out of	Sequence				

Lug Extrusion

D3394-3P

Location HALL

No

Purchased

105422

Loc Qty 171.666848 171.666848

170

Each


0.0000


Loc Code


**


Lug

DQA:			Date:										
						WORK ORDER NON-	-CO	ONFO	RMANCE / U	PDATE			AEROSPACE
QA Closed:			Date:							V	ork Order up	odate only	
						DISPOSITION				AGAINST D	EPARTMENT	/PROCESS	
Work Orde	er:						,				 ¬	_	
:						Rework			Skid-tube	Crosstube		Water Jet	Engineering
Part N	10.					Scrap			Machining	Small Fab	_	d. Eng. Coor.	Quality
						Use-as-is		Thern	noforming	Finishing	Rec/Sto	re/Packaging	Other
NCR N	10.					Suspected Unapproved]		Large Fab	Composite		Supplier	
Root					Desc	ription of work order update		Initial	Act	tion	Sign &		
Cause		Date	Step	Qty		or non-conformance		nief Eng	l .	ription	Date	Verification	QC Inspector
Design													
Doc/Data							1						
Equip/Tooling													
Handling/Pre													
Material													
Operator							İ						
Offset/Setup							l						
Process									<u> </u>				
Supplier													
Training													
Transport			!										
Unapproved											<u> </u>		
							FAI	ULT CAT	regory				
Landi	ng (1			_	General		3		_	7		-
		Bending			<u> </u>	Bend	<u></u>	1	Program	_	Outside Dim	<u> </u>	Pressure/Forced
	_	Centre No	ot Concen	itric		BOM/Route	<u></u>	Grain			Over/Under	<u> </u>	Set-up
		Cracks				Broken/Damage/Defect	<u> </u>	Hardwa		<u> </u>	Part Incorre	 	Temperature/Cure
		Crimp/Kir	nk/Ripple,	/Wave	<u> </u>	Burrs	<u> </u>	1 '	ion Incomplete/Ur	· –	Part Lost/Mi	ssing	Weld
		Cuffs				Contamination	<u></u>	4	tions Incomplete/U	Jnclear	Part Moved	L	Wrong Stock Pulled
		Crushing				Countersink	<u> </u>	-	ned/off center	<u> </u>	Positioned V		¬
		Heat Trea			<u> </u>	Cut Too Short	<u> </u>	Mislabe		L	Power Loss/	Surge	Other
		Inspection	-	Tube		Drawing	\vdash	Misread					
		Marks/Ch			<u> </u>	Drill Holes	<u> </u>	Off-set				-	
		Turning S			<u> </u>	Finish	\vdash	4	Calibration				
[Wave/Tw	ist in Tub	e		Fit/Function	1	JOut of S	Sequence				









£								
DRAWING NO.			REV. B	DART AEROSPACE LTI	D.E.O. NO.	-	SHEET NO.	SCALE
D3394	LUG			ENGINEERING PROER	D3394-B-	1	SHEET 1 OF 1	NTS
DRAWN	AJS	CHECKED	<u>k</u>	MFG. APPR.	APPROVED .	MD.	DE APPR.	
DATE 0	9.11.04	DATE GW 64		DATE 09-11.04.	DATE Ø	4/11/04	DATE 09/11/04	
1			_			,		
•		Si	HEET 4 ZONE	A,1 MODIFY SECTION A-A AS S	SHOWN:			
IS:				1				i
· 				RO	UND SHARP ED	GE		
İ				<u>∕</u> − R0.	06 - 0.10			1
				2 P	L			
ļ								
1								
:								
I								
Ì								
				SECTION A-A				
1				OLOHOHAA				
WAS:			•					
MAO.	-							
ı				R0.1	25			
				2 PL				
;							FIEAGE	
						K	ELEASED 2009 -11-25	
•						9 (2009 -11- 25	
							, , 1	
1							TW	
1								
				KX/X)				
1				SECTION A-A				
!				REASON: DRAFTING ERROR		332.		
							UT @ 2000 BY DART AEDOCRACE LT	

COPYRIGHT © 2009 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COMPUTATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD.


DRAWING N	NO. TITLE	REV. B	DART AEROSPACE USA	A, INC D.E.O. NO.	SHEET NO.	SCALE
D3394	LUG		ENGINEERING ORDI	R D3394-B-2	SHEET 1 OF 1	NTS
DRAWN	P	CHECKED SC	MFG. APPR.	APPROVED N	DE APPR.	
DATE	11.05.02	DATE 11.05.09	DATE //.05.08	DATE 11.05.08	DATE 11.05.09	

PURPOSE

ADD D3394-xRG OPTION

CHANGE

D3394-xRG MOUNTING LUGS ARE INDENTICAL TO D3394-x MOUNTING LUGS, HOWEVER AFTER FINISH, COAT INNER CONCAVE SURACE WITH "PLUS ONE ROCKGUARD 4714" AS SHOWN BELOW.



RELEASED 2011-05-2

D3394-1RG LUG (SHOWN)
D3394-3RG/-5RG LUGS (SIMILAR)
D3394-041RG/-043RG/-045RG LUG ASSEMBLIES (SIMILAR)

COPYRIGHT © 2011 BY DART AEROSPACE USA, INC CLICKIT IS PRIVATE AND COMPIDENTIAL AND IS SUPPLED ON THE EXPRESS CONTINUED THAT IT IS HE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATE TO ANY OTHER PERSON WITHOUT



Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7

Tel: 613 632 9577 Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO24014

Purchase Order Date 4/30/2014 PO Print Date 4/30/2014

Page Number 1 of 2

Order From:

A.T.G. INDUSTRIES INC. 731 INDUSTRIELLE ROAD ROCKLAND, ON K4K 1T2 CANADA VC-ATG001

Ship To:

DART AEROSPACE LTD

1270 ABERDEEN

HAWKESBURY, ON K6A 1K7

CANADA

[-04/04/30]

Contact Name

Vendor Phone

Ship To Contact

Ship To Phone

Ship Via:

Ship Acct:

B116859

613-446-4544

VENDOR'S TRUCK

Buyer

Chantal Lavoie

Customer POID

Customer Tax #

10127-2607

Terms

Net 30

Currency

CAD

FOB

FCA - (Free Carrier)

Line Nbr	Reference Vendor Part Number Line Comments Delivery Comments	Description/ Mfg ID	Req Date/ Taxable Promise Date	CD	Req Qty/ Unit of Measure	,	PO Unit Price	Extenda Pri
1	D2731-7P	Lug	5/23/2014 Yes 5/23/2014		50.00 Each		\$11.00	
	MACHINE AS PER DWG D2 B116802	731 REV. C	5,25,252			8P/1	4-le-3	
							Line Total:	\$550.0
2	D3394-3P	Lug	5/23/2014 Yes 5/23/2014		40.00 Each		\$12.00	\$480.(
	MACHINE AS PER DWG D3	3394 REV. B		•				

Line Total:

\$480.

Note:



A.T.G. INDUSTRIES INC. 731 INDUSTRIELLE STREET ROCKLAND, ON-K4K 1T2 Canada

Ph: (613) 446-4544 Fax: (613) 446-4556

Pack List

Number: 908034

Date: 06-Jun-14

To

DART AEROSPACE LTD 1270 ABERDEEN STREET HAWKESBURY, ON K6A 1K7 Canada Ship To

CHANTAL LAVOIE
DART AEROSPACE LTD
1270 ABERDEEN STREET
HAWKESBURY, ON K6A 1K7
Canada

Ph: 613 632-9577

Fax: 613 632-1053

Ph: 613 632-9577

Fax: 613 632-1053

				1
Terms		Ship Via		1
Quantity	Description			
	PLEASE REFERENCE THE PACK LIST N SHIPMENT. IF YOU HAVE ANY QUESTIONS, PLEASE		NDENCE TO THIS	
40	Part: D3394-3P	·····	Rev: B	1 2
· ea	LUG			
	Job: 16230	PO: PO24014	Line: 2	. American
	DATE : 0 Le Sume 2 CERTIFIED SIGNATURE:	sig supott		The second second
	RECEIVER SIGNATURE CERTIFICATE O	CYBULE OF CONFORMANCE		Acceptable of control services
	A.T.G. INDUSTRIES INC. CERTIFIES THA CONFORMANCE WITH THE REQUIREME REFERENCED IN THE ABOVE PURCHAS	AT ALL ITEMS IN THIS SHIPM ENTS, SPECIFICATIONS, ANI		And the state of t
	·			Odinatensy was the standard to the
·	· .			
				en particular establication constitution of the constitution of th
				The state of the s

First Article Inspection Report



731 Industrielle St Rockland, Ontario K4K 1T2 Ph: 613 446-4544

 Customer:
 Dart Aerospace
 Date:
 May 22nd, 2014
 496

 Part Number:
 D3394-3P
 Revision:
 B

 PO Number:
 PO24014
 Qty:
 40
 FAI No.

Dimension	Measurement Inspected by: Rene Tougas,		Remark	
	Inspected by Pone Touges		Kemark	ς.
1 4.450	inspected by Kene Tougas,	Q.C.	- Remark	
4.450	4.450			
.100 REF	✓			
R.125 REF	✓			
.157	.159			
.306	.308/.292			
1.91 REF	1.914			
Note 6	√			
.400	.398			
.250	.250			
.735 REF	.724			***************************************
Machine to Size	✓			
.345	.348			
R1.100	✓			
R1.250 REF	R1.250			
Machine to Size	✓			
· The second constant of the second constant	and the state of t			
Ø.453	Ø.453		- And Annual Control of the Control	
Ø.750				
- The state of the				
.375	.375			and a state of the second
3.700	3.698			
R.375 REF	.375			
Ø.257+.005/.000	.261			·
.750	.750			
			Administration of the second	and the second s
Material			Supplied by Cu	tomer
Chem Film			In House	
Paint			Supplied by Cus	tomer
	R.125 REF .157 .306 1.91 REF Note 6 .400 .250 .735 REF Machine to Size .345 R1.100 R1.250 REF Machine to Size Ø.453 Ø.750 .375 3.700 R.375 REF Ø.257+.005/.000 .750 Material Chem Film	R.125 REF .157 .159 .306 .308/.292 1.91 REF 1.914 Note 6 .400 .398 .250 .250 .735 REF .724 Machine to Size .345 .348 R1.100 R1.250 REF R1.250 Machine to Size ∅.453 ∅.750 .375 .375 .375 .370 .375 .375 .375 .375 .375 .375 .375	R.125 REF .157 .306 .308/.292 1.91 REF 1.914 Note 6 .400 .398 .250 .735 REF .724 Machine to Size .345 R1.100 R1.250 REF Machine to Size Ø.453 Ø.750 Ø.453 Ø.750 R.375 3.700 R.375	R.125 REF .157 .159 .306 .308/.292 1.91 REF